

GE 159 Plastics Avenue Pittsfield, MA 01201 USA

Transmitted via Overnight Courier

October 2, 2007

Ms. Dale C. Young Lead Administrative Trustee Massachusetts Executive Office of Environmental Affairs 100 Cambridge Street, Suite 900 Boston, Massachusetts 02114-2119

Re: GE-Pittsfield/Housatonic River Site

Newell Street Area II (GECD450)

Summary of September 2007 Inspection of the Natural Resource Restoration/

**Enhancement Area** 

Dear Ms. Young:

On September 5, 2007, the General Electric Company (GE) performed the second inspection of areas subject to natural resource restoration/enhancement (NRRE) measures at Newell Street Area II. As shown on Figure 1, areas subject to NRRE measures include the majority of the GE-owned Newell Street parking lot area and a portion of the "wooded area" at Parcel J9-23-12. These measures consisted of the following:

- The planting of an herbaceous native grassland community on the surface of the vegetative engineered barrier at the Newell Street parking lot area (excluding the paved access road), as well as in a portion of the wooded area on Parcel J9-23-12 shown on Figure 1, using a mixture of native grass and wildflower species proposed in the Addendum and approved by EPA.
- The installation of a bluebird box along the edge of the former parking lot area adjacent to the Housatonic River.

In accordance with the Natural Resource Trustees' (Trustees') June 10, 2005 letter, GE did not place stumps and rock piles within the NRRE areas.

GE conducted the initial inspection of areas subject to NRRE measures at Newell Street Area II on June 20, 2007. A summary of the June 2007 inspection activities was submitted to the Trustees (with copies to EPA and the Massachusetts Department of Environmental Protection [MDEP]) in a letter dated August 3, 2007.

## **Summary of Inspection Activities**

Consistent with the initial inspection, the September 2007 inspection was conducted in accordance with the requirements for such inspections set out in the Restoration Project Monitoring and Maintenance Plan (Restoration M&M Plan) provided as Attachment A to the Final RD/RA Work Plan Addendum for Newell Street Area II. Inspection activities consisted of a field inspection and survey of the planting areas to: (a) verify aerial coverage by herbaceous species; (b) determine any evidence of trespassing or herbivory; (c) assess the apparent vigor of the vegetation; and (d) inspect for the presence of invasive species (as listed in the Restoration M&M Plan).

The results of the September 2007 inspection are documented in a Natural Resource Restoration/Enhancement Inspection Checklist and accompanying photographs. Copies of the completed checklist and the photographs are provided in Attachments A and B, respectively.

In addition, the September 2007 inspection included observations of areas where any follow-up activities were identified during the June 2007 inspection. No follow-up activities were identified during the June 2007 inspection. A summary of the follow-up activities identified during the September 2007 inspection is provided below.

# **Summary of Observations During Inspection**

As indicated in the Restoration M&M Plan, any herbaceous planting area within the NRRE areas with less than 100% cover will be supplemented with additional planting and seeding. In summary, the recent inspection results concluded that the majority of the subject area contains less than 100% herbaceous cover. The inspection indicated the presence of different stages of vegetation establishment within three portions of the NRRE areas. The northeastern portion of the Newell Street parking lot area and a portion of the "wooded area" exhibited approximately 80% ground cover, with 50% of the species observed from the seed mix. The northern portion of the Newell Street parking lot area exhibited approximately 60% ground cover, with 75% of the species observed from the seed mix. The western portion of the Newell Street parking lot area exhibited approximately 50% ground cover, with 75% of the species observed from the seed mix.

In response to the above observations, GE proposed, in separate communications with the Trustees and EPA, a plan to conduct sampling of the upper three inches of topsoil within the NRRE areas for pH and pK analyses. These analyses will aid in the determination of what factors may be restricting the growth and promulgation of desired herbaceous species. Subsequent to the review of the above referenced analyses, GE proposed to augment, if necessary, the nutrient levels and/or balance pH levels of soils within the NRRE areas and determine whether the addition of mulch is necessary. Following completion of the above activities, GE proposed to reseed portions of the NRRE areas showing deficient herbaceous cover. Reseeding activities are anticipated to include scarifying the surficial soil and applying the approved seed mix at approximately 25 pounds per acre, consisting of 15 pounds per acre of the approved seed mix and 10 pounds per acre of rye seed. The above activities are anticipated to be initiated during fall 2007.

No significant signs of herbivory or stress were observed in the developing plant communities. None of the invasive species listed in the Restoration M&M Plan were observed within the NRRE areas, although some invasive species were present in undisturbed vegetated areas adjacent to the NRRE areas. Since the NRRE areas are surrounded by a locked chain-link fence (except along the river) restricting trespasser access, no signs of damage from trespassers was observed.

### **Schedule of Future Inspections**

The Restoration M&M Plan provides that monitoring activities are to consist of two site visits during each of the first three years after planting, one visit during the fifth year after planting, and one visit during the seventh year after planting. In each of the first three years after planting, visits are to be conducted in the late spring after the first leaf flush (May/June) and in the summer (July/August) to assess plant survival. The single visit in the fifth and seventh year after planting is to be conducted in the summer (July/August). Following each inspection, an inspection report is to be prepared and submitted to the Trustees (through the Lead Administrative Trustee), with copies to EPA and the MDEP.

Please call me if you have any comments or questions.

Sincerely,

Richard W. Gates

Remediation Project Manager

Richard W. Gates/FGB


### Attachments

Dean Tagliaferro, EPA cc: Richard Fisher, EPA Tim Conway, EPA Holly Inglis, EPA Rose Howell, EPA\* Linda Palmieri, Weston (2 copies) Anna Symington, MDEP\* Jane Rothchild, MDEP\* Susan Steenstrup, MDEP (2 copies) Mike Chelminski, Woodlot Alternatives, Inc. Mayor James Ruberto, City of Pittsfield Nancy E. Harper, MA AG\* Michael Carroll, GE\* Andrew Silfer, GE Rod McLaren, GE James Nuss, ARCADIS BBL James Bieke, Goodwin Procter Public Information Repositories GE Internal Repositories

<sup>\*</sup> without attachment



Figure



# **ARCADIS** BBL

### Attachment A

Completed Inspection Form

# NATURAL RESOURCE RESTORATION / ENHANCEMENT INSPECTION SUMMARY AND CHECKLIST

### **NEWELL STREET AREA II REMOVAL ACTION**

### PARCEL J9-23-12 (PARKING LOT AREA AND PORTION OF WOODED AREA)

I. GENERAL INFORMATION	
Inspection Date:	September 5, 2007
Conducted By:	Anthony Esposito Phone Number: (315) 671-9268
Weather Conditions:	Sunny, 70 degrees F
Date of Last Inspection:	June 20, 2007
II. INSPECTION SUMMARY	
1. Groundcover	
A. Estimated Groundcover (Note a percentage of groundcover by herbaceous species; note evidence of areas of bare/sparse vegetation; note any damage from trespassing or herbivory; note any physical changes since last inspection, etc.)	
	on of Newell Street parking lot area and portion of the "wooded area" - 80% total groundcover; 50% from seed mix.
	f Newell Street parking lot area - 60% total groundcover; 75% from seed mix.
	Newell Street parking lot area - 50% total groundcover; 75% from seed mix.
· ·	road installed since last inspection (see 3 below).
remperary access	road mataned amor has mapochem (add a below).
B. Presence of Inva	sive Species (Note a percentage of area occupied by invasive species; note the species present including but not
	wing: Amur honeysuckle, Autumn olive, Black locust, Black swallow-wort, Common barberry, Common buckthorn,
	ossy buckthorn, Goutweed or Bishop's weed, Japanese barberry, Japanese honeysuckle, Japanese knotweed,
Morrow's honeysuckle, Morrows' X Tartarian honeysuckle [hybrid], Multiflora rose, Norway maple, Oriental bittersweet, Phragmites -	
Reed grass, Porce	elain berry, Purple loosestrife, Russian olive, Tartarian honeysuckle, or Yellow iris, etc.)
None of the listed	species were observed in the NRRE areas.
	e inspected on a yearly basis for 3 years. (Note any evidence of damage and the extent of damage such as the
need to be replace	nspected annually during the spring inspection).
14/1 (blacbild box ii	ispected difficulty during the spring inspection).
3. Other Observation	ns (Confirm that repair/maintenance measures identified during prior inspection have been performed; note any
other general obse	ervations, including parcel-specific restoration activities.)
Temporary access	road was installed from the north end of the asphalt access road to just south of the riverbank and extended
east and west.	, , , , , , , , , , , , , , , , , , , ,
III. FOLLOW-UP MAIN	ITENANCE AND REPAIR ACTIVITIES
-GE proposes to c	onduct sampling of the upper three inches of topsoil within the NRRE areas for pH and pK analyses.
Subsequent to the	e review of the above referenced analyses, GE proposes to augment, if necessary, the nutrient levels and/or
	of soils within the NRRE areas and evaluate the need for addition of mulch.
	tion of the above activities, GE proposes to scratch and reseed portions of the NRRE areas showing deficient
herbaceous cover	· · · · · · · · · · · · · · · · · · ·
-The above activiti	es are anticipated to be initiated during fall 2007.

## ATTACH ADDITIONAL INFORMATION AS APPROPRIATE

# **ARCADIS** BBL

## **Attachment B**

Photo Log



Photo #1: Northeast portion, looking east.



Photo #2: Northern portion, looking west.

Client: General Electric Company
Project Name: Newell Street Area II
Project Location: Pittsfield, Massachusetts

ARCADIS BBL



Photo #3: Vegetation of the fenced enclosure, looking south.



Photo #4: Vegetation of the fenced enclosure, looking southwest.

Client: General Electric Company
Project Name: Newell Street Area II
Project Location: Pittsfield, Massachusetts

ARCADIS
BBL



Photo #5: Southern portion, looking south.



Photo #6: Western portion, looking west.

Client: General Electric Company
Project Name: Newell Street Area II
Project Location: Pittsfield, Massachusetts

**ARCADIS** BBL



Photo #7: Area immediately northwest of the northwest corner of the fenced enclosure, looking north.



Photo #8: Drainage ditch east of the access road, looking north.

Client: General Electric Company Project Name: Newell Street Area II

Project Location: Pittsfield, Massachusetts

**ARCADIS** BBL